VISIBLE EMISSION NOTATIONS				
Inspector: Smelko				
Date of Inspection:	.15			
Shift: 1st Shift or 2nd Shift	Time:	5:AM		
Unit	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nur			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Cours e A	Sanctice	·		
Date of Inspection: 7/1/16				
Shift: 1st Shift or 2nd Shift	Time:	5260 pm		
Unit is	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor		÷	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

١	/ISIBL	F	E٨	/IISSION	NOTAT	IONS

Visible Emission From Discharge

Conveyor System

Inspector: Greorge A)	ancher				
Date of Inspection: 1/2/12					
Shift: (1st Shift) or 2nd Shift	Time:	5:00			
Unit and the second sec	Visual Inspection NORMAL or ABNORMAL		Comment	S and the second	
Visible Emission From Shaker	./				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Smel	KO			
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	t Time:	AM		
Unit <sub>1</sub>	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments.	
Visible Emission From Shaker	nor	***		
Visible Emission From Discharge Conveyor System	nor	Manager .	·	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMI	SSION	NOTAT	IONS
-------------	-------	-------	------

Inspector: Smelko			_		
Date of Inspection:	5, 15				
Shift: 1st Shift or 2nd Shift	Time:	SAM			
Unit	Visual Inspection NORMAL or ABNORMAL			omments	
Visible Emission From Shaker	noR	wilderstrage			
Visible Emission From Discharge Conveyor System	nor	None .			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



Per Each Daylight Shift

Inspector:	Constan			
Date of Inspection:	15			
Shift: 1st Shift or 2nd Shift	Time:	5PM	,	
Unit	Visual		Comments	
	Inspection		Andreas (1971), a series de la companya de la comp La companya de la co	
	<u>NORMAL</u>			
	or			
	<u>ABNORMAL</u>			
Visible Emission From Shaker		740		
	No./			
Visible Emission From Discharge				
Conveyor System	$N_{a}$	Appropriate Control of the Control o	September 12 (EST)	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(STOCK SE

VISIBLE EMISSION NOTATIONS	·		_	
Inspector:	Compton			
Date of Inspection: 7/5//	5			
Shift: 1st Shift or 2nd Shift	Time:	5 PM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nov	The state of the s		
Visible Emission From Discharge Conveyor System	Nov	particular de la constitución de		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE LIVISSION NOTATIONS			<b>_</b> :		
Inspector: George AS	emeher				
Date of Inspection:	inco.				
Shift: 1st Shift or 2nd Shift	t Time:	5:00 pm			
Unit.s	Visual Inspection <u>NORMAL</u> or ABNORMAL			omments	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Wor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Smelko				
Date of Inspection:	2.15			
Shift: 1st Shift or 2nd Shift	Time:	SAM		
Unit.	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments.	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	nor		·	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Alex Bank	istu			
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	Time:	5.30An		
Unit :	Visual Inspection NORMAL or ABNORMAL		mments	
Visible Emission From Shaker	NOR	·		
Visible Emission From Discharge Conveyor System	Noc			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

#### **VISIBLE EMISSION NOTATIONS**

Nor

Inspector: Creorge A Sun	hec			
Date of Inspection: 7/4/15				
Shift: Ast Shift or 2nd Shift	t Time:	5:00 pm		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Wor			
Visible Emission From Discharge			-	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Conveyor System





(Stack SDS 04)

Inspector: Alex B	,			
Date of Inspection: 7/8/	45			
Shift: 1st Shift or 2nd Shift	Time:	5:30An		
Unit in the second seco	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments .	
Visible Emission From Shaker	NUR	<sup>Q-la</sup> ndhelmennennen	·	
Visible Emission From Discharge Conveyor System	NOR	Management		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: George A Sono	her		]		
Date of Inspection: 4/8/15					
Shift: (1st Shift) or 2nd Shif	t Time:	5:00 pm			
	Visual Inspection <u>NORMAL</u> or ABNORMAL		Co	omments	
Visible Emission From Shaker	Nor				er generale in the green from the secretary against a secretary as a construction of a process from the green a
Visible Emission From Discharge Conveyor System	Nor			-	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



(Stack SDS 04)

VISIBLE EIVISSION NOTATIONS				
Inspector: Paul Larl				
Date of Inspection: 7-9-15				
Shift: 1st Shift or 2nd Shift	t Time:	5090-		
Unit s	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		mments	
Visible Emission From Shaker	Nov	·		
Visible Emission From Discharge	Nov			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

١	/ISIBL	F	F٨	1155	ION	NO	ΓΔΤ	IONS
٦	/ 1.511.51.	. L_	$-$ L $^{1}$	/1133	IOIA	140	I /~\ 1	UVIVJ

Visible Emission From Shaker

Conveyor System

Visible Emission From Discharge

Nor

Inspecto	or: beorg	e a	4 Sans	hoe					
Date of I	Inspection:	7	1/9/15						
Shift:	1st Shift	or	2nd Shift	Time	5:00pm	!			
	Uni	t V		Visual Inspection NORMAL or			Comment		


• Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

• Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector:	- Cre		]		
Date of Inspection:			1		
Shift: 1st Shift or 2nd Shift	Time:	~~			
Unit	Visual Inspection: <u>NORMAL</u> or ABNORMAL		Con	mments	
Visible Emission From Shaker	Nor	· .			
Visible Emission From Discharge Conveyor System	nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



(Stack SDS 04)

#### **VISIBLE EMISSION NOTATIONS**

Visible Emission From Shaker

Conveyor System

Visible Emission From Discharge

Inspector: George A Sanch	ec	
Date of Inspection: 7/16/15		
Shift: 1st Shift or 2nd Shift	Time: 5-00pm	
Unit	Visual Inspection Inspection	Comments

or ABNORMAL

Nor

Nor

• Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

• Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





THORSE ENGINEER THORSE		<del>,</del>	
Inspector:			
Date of Inspection:			
Shift: 1st Shift or 2nd Shift	Time:		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>	Comments	
Visible Emission From Shaker			
Visible Emission From Discharge Conveyor System			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIDEL LIVISSION NOTATIONS					
Inspector:	1 Compto-	politica (m. )			
Date of Inspection: 7/12	1,5				
Shift: 1st hift or 2nd Shift	Time:	5pm			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments	
Visible Emission From Shaker	No-	**************************************	paragrammanappilantis 4-dimensional accommunity (inches),		
Visible Emission From Discharge Conveyor System	n/ -			- Control of the Cont	


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

1101222 211110010111110110				
Inspector: Smelko				
Date of Inspection: July 13	,15			
Shift: 1st Shift or 2nd Shift	Time:	SAM		
Unit	Visual Inspection NORMAL Or ABNORMAL		Comments	
Visible Emission From Shaker	noR			
Visible Emission From Discharge	noR	- Tempo,		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS				
Inspector:	Captan			
Date of Inspection:	15#			
Shift: 1st Shift or 2nd Shift	Time:	5PM		
Unit Control of the C	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	No		Manage de la constante de la c	
Visible Emission From Discharge Conveyor System	N.	A CONTRACTOR OF THE PARTY OF TH	And the state of t	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

5 of 6

(Stack SDS 04)

Inspector: Smelko				
Date of Inspection:	15		1	
Shift: 1st Shift or 2nd Shift	Time:	5-		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	RUP			
Visible Emission From Discharge Conveyor System	nor	amagasar		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Ser	remy Hardin				
Date of Inspection: 7/15	115				
Shift: 1st Shift or 2	nd-Shift Time:	600am			
Unit  Visible Emission From Shak	Visual Inspection NORMAL or ABNORMAL er		Comme	ents	
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		<u> </u>			
Visible Emission From Disch	narge   Normal				
Conveyor System	1 Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE	E EM	ISSION	NOT	ATIONS
---------	------	--------	-----	--------


VISIBLE EIVIISSION NOTATIONS				
Inspector: Smelko				
Date of Inspection: July 16	1 5			
Shift: (1st Shift) or 2nd Shift	Time:	51		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOP	ordinando.		
Visible Emission From Discharge	nor	Name.		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE LIVINGSION NO INTRONS					
Inspector:	Convoto -	-			
Date of Inspection: 7/16 /	1,50				
Shift: 1st Shift or 2nd Shift	t Time:	SAM		·	
Unit.	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Communication of the state of t	ments	
Visible Emission From Shaker	No		50000000000000000000000000000000000000		
Visible Emission From Discharge Conveyor System	Not		halicoppoparative accomplication of the Commission of the Commissi		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





1101022 21111001011 11011111110110					
Inspector:	d Comton				
Date of Inspection:	50				
Shift: 1st Shift or 2nd Shift	ft Time:	SAM			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			mments.	
Visible Emission From Shaker	No		99000000000000000000000000000000000000		
Visible Emission From Discharge Conveyor System	No	, production of the second	Sharen and the state of the sta		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE	<b>EMISSION</b>	<b>NOTATIONS</b>
---------	-----------------	------------------

Inspector: Smelko					
Date of Inspection: July 17	, 15		]		
Shift: 1st Shift or 2nd Shif	t Time:	5,00	Ĩ		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Com	nments	
Visible Emission From Shaker	nor				
Visible Emission From Discharge Conveyor System	nov				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

# D.1.12 SDS | Daily Visible Emissions Notations Per Each Daylight Shift (Stack SDS 04)

Inspector: Garge A Sar	rehez				
Date of Inspection: 4/18/65					
Shift: 1st Shift or 2nd Shift	t Time:	5100 por			
Unit.	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			mments.	
Visible Emission From Shaker	Nor	·			
Visible Emission From Discharge Conveyor System	Nor		:		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Paul Lark						
Date of Inspection: 7-18-15			-			
Shift: 1st Shift or 2nd Shift	Time:	5:00 Am	-   			
Unit	Visual		en e	Comments	in the spirit of the property of the spirit	Alleria (2007)
	Inspection	200				
	<u>NORMAL</u>					
	or <u>ABNORMAL</u>			and a superior bracks of the		1915 M. T.
Visible Emission From Shaker	Nor					
Visible Emission From Discharge				,		
Conveyor System	Nor					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBL	E EMISSIO	N NO	TATIONS			
Inspect	Creos	rg e	A San	her		
Date of	Inspection:	7/1	19/15			
Shift:	Lst Shift	or	2nd Shift	Time	: 5:00 pm	
	Шhi	t iii		Visual	rist in the state of the state of the	

Chit	Visual	Comments 22
	Inspection	
	<u>NORMAL</u>	
	OT-	
	ABNORMAL	
Visible Emission From Shaker	Nor	
Visible Emission From Discharge	41	·
Conveyor System	Nor	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE EMISSION NOTATIONS				
Inspector: Vaul Lork				
Date of Inspection:				
Shift: 1st Shift or 2nd Shif	t Time:	5=00 Am	 	
Unit	Visual Inspection NORMAL Or		Comments	
Visible Emission From Shaker	ABNORMAL			
Visible Emission From Discharge Conveyor System	NOT			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



light Shift

**VISIBLE EMISSION NOTATIONS** 

Visible Emission From Discharge

Conveyor System

Nor

Inspector: Prope & Sunfer						
Date of Inspection: 7/20/4	5					·
Shift: 1st Shift or 2nd Shif		5:00 pm				
	Visual Inspection	10 (10 (10 (10 (10 (10 (10 (10 (10 (10 (		Comments		
and the second s	<u>NORMAL</u>	der	Part of the second of the seco		Single Court of	
	ABNORMAL					
Visible Emission From Shaker		A STATE OF THE STA				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

	· · · · · · · · · · · · · · · · · · ·		1		
Inspector: Smelko					
Date of Inspection:	か				
Shift: 1st Shift or 2nd Shift	Time:	SOUAM			
Unit	Visual		The state of the s	omments	
	Inspection				1766 (1) 10 10 10 10 10 10 10 10 10 10 10 10 10
	<u>NORMAL</u>	10 mm	Manager 1996 To 1997 The Control of		
	or				
	<u>ABNORMAL</u>		general Company of the Company		
Visible Emission From Shaker	nur	·			
Visible Emission From Discharge	000				
Conveyor System	1/01				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Grosse & Sarch	, 07				
Date of Inspection: 4/21/15			- Carlos		
Shift: 1st Shift or 2nd Shif	t Time:	5:00 pm			
Unit	Visual Inspection <u>NORMAL</u> IOT ABNORMAL			Comments	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

#### D.1.12 SDS I Daily Visible Emission Stations Per Each Daylight Shift (Stack SDS 04)

VISIBLE EMISSION NOTATIONS				
Inspector: Smello				
Date of Inspection:	,15			
Shift: 1st Shift or 2nd Shift	t Time:	5:0-		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	nor	ggeddesson		
Visible Emission From Discharge Conveyor System	nor	•		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

# D.1.12 SDS I Daily Visible Emissions Stations Per Each Daylight Shift (Stack SDS 04)



Inspector: George A Sans	hoc			
Date of Inspection: 4/22/15		777		
Shift: 2st Shift or 2nd Shif		5:00 pm		
Unit.	Visual Inspection		::: Comments	
	. NORMAL			
	OT ABNORMAL	The state of the s		
Visible Emission From Shaker	Ner		V 3 500 1	
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS					
Inspector: Paul La M					
Date of Inspection:	5				
Shift: 1st Shift or 2nd Shift	Time: ¿	5:00 AM			 
Unit	Visual Inspection NoriMal Or ABNORMAL			Comments	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge	Nov		•		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

### **VISIBLE EMISSION NOTATIONS**

Visible Emission From Shaker

Conveyor System

Visible Emission From Discharge

Nor

Nor

Inspec	tor: (700°5.	e Danc	hoc							
Date o	f Inspection:	4/23/1	5							
Shift:	1st Shift	or 2nd Sl	hift T	ime: S. OOpen						
	Uhit		Visual Inspection			en e	Comments		K.	14
	The state of the s		<u>NORMAL</u>							
			L COL	March 1997	444			l) vezi tr		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

### VISIBLE EMISSION NOTATIONS

Inspector: Smelko					
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time:	54m			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		C	omments	
Visible Emission From Shaker	108	And the second second			
Visible Emission From Discharge Conveyor System	nor	45.			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Carge of Souch	ee				
Date of Inspection: 4/21/15	-		- 		
Shift: Ast Shift or 2nd Shift	t Time:	5:00pm			
Unit:	Visual Linspection <u>NoRMAL</u> or ABNORMAL			mments	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor		•		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



Inspector: Smelto		a physical and the state of the			
Date of Inspection:	,15				
Shift: 1st Shift or 2nd Shift	t Time: -	SAM			
Unit .	Visual Inspection <u>NORMAL</u> For ABNORMAL			Comments	
Visible Emission From Shaker	nor				
Visible Emission From Discharge Conveyor System	noR	Amount of the Control	• .		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

# D.1.12 SDS I Daily Visible Emissions For Each Daylight Shift (Stack SDS 04)

VISIBLE EMISSION NOTATIONS

Inspector:

Pack & Surface

Date of Inspection:

Shift: 1st Shift or 2nd Shift

Visual

Inspection:

NORMAL

Visible Emission From Shaker

Visible Emission From Shaker

VISIBLE EMISSION NOTATIONS

Inspector:

Visual

ABNORMAL


Visible Emission From Shaker

Von

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Visible Emission From Discharge

Conveyor System






Inspector: Smelto	-				
Date of Inspection: July 26	, 15				
Shift: 1st Shift or 2nd Shift	t̃ Time: ≺	SAM			
Uhit.	Visual Linspection NORIMAL Or ABNORIMAL			Comments	
Visible Emission From Shaker	nor	screen francisco com-			
Visible Emission From Discharge Conveyor System	nor	and the second	•		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Chesic A Sarch	eC				
Date of Inspection: 4/16/15					
Shift: (1st Shift) or 2nd Shift	t Time:	5:00 pm	 	_	
:Uhit	Visual Inspection <u>NORMAL</u> = Or		Comments		
Visible Emission From Shaker	Nor ABNORMAL				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



Inspector:						
M. PHILLIP	<u> </u>					
Date of Inspection:						
7-27-15						
Shift: (1st Shift) or 2nd Shift	t Time:	9',00 AM				
Age Writer	Visual	T 1257		Comments	and the second second	
	Inspection		and the second	n en		
	<u>NORMAL</u>					
	10.					
	<u>ABNORMAL</u>					
Visible Emission From Shaker	.0.	And the state of t				
	PORMAL	·				
Visible Emission From Discharge	\	٠	•			
Conveyor System	NORMAL			. •		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector: Vaul (A	Y				
Date of Inspection:	5				
Shift: 1st Shift or 2nd Shif	Time:	5-00 AM			
Olific.	Visual Inspection <u>(NORMAL</u> Or			omments	
	ABNORMAL		1987 (1984) 1987 (1984)		
Visible Emission From Shaker	Nov				
Visible Emission From Discharge Conveyor System	Nor		,		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



# D.1.12 SDS I Daily Visible Emissions Per Each Daylight Shift (Stack SDS 04)



Inspector: Smello				
Date of Inspection: Tely 28	5,13		-	
Shift: 1st Shift or 2nd Shift	Time:	5:00		
Unit 4	Visual Inspection NORMAL Or ABNORMAL		Commen	
Visible Emission From Shaker	noB	manager (Filterina)		
Visible Emission From Discharge Conveyor System	nor	Манто		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

				– – .	
VISIE	SIF	FΜI	รรเดพ	$NOT\Delta$	TIONS

TIGIBLE ENTIRETOTI TO TITTOTIC				
Inspector: Greene A Sanc	her			
Date of Inspection: 4/29/15				
Shift: 1st Shift or 2nd \$hi	t Time:	5: 60 year		
Unit Programme Control of the Contro	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

١	/19	1	R	ΙF	F٨	1	ISS	ION	N	$\cap$	ΓΔ	Т	$\cap$	N	ς
ı,	/ I.	3 (	1.	டட		7 t 1		$-10^{\circ}$		$\mathbf{C}$	_		_	1 V	_

7.0.022 2,7.1.00.01.1.10.7.1.0.1.0		
Inspector: Greene A San	her	
Date of Inspection: 7/30/65		
Shift: 1st Shift or 2nd Shift	Time: 5:00,sm	
Unit	Visual Inspection NORMAL or ABNORMAL	Comments
Visible Emission From Shaker	Nor	
Visible Emission From Discharge	Nor	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: W. Zank	1150			
Date of Inspection:	1/15			
Shift: 1st Shift or 2nd Shif	t Time:	500		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Normal			
Visible Emission From Discharge Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE EMISSION NOTATIONS			_		
Inspector:	Medano				
Date of Inspection: 7-31-1	5 5	5.00pm			
Shift: 1st Shift or 2nd Shift	t Time:				
Unit 1	Visual Inspection			Comments	
	<u>NORWAL</u>				
	ABNORMAL	The specific of the specific o		SERVICE CONTRACTOR	Artista (September 1997) Portugues (Artista)
Visible Emission From Shaker	norm				
Visible Emission From Discharge					
Conveyor System	Morm				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.